

ABSTRACT OF THE DISCLOSURE

After a metal member of an alloy containing copper and nickel is arranged on at least one side of a ceramic substrate, the metal member and the ceramic substrate are
5 heated in an atmosphere of an inert gas or in vacuo at a temperature between solidus and liquidus lines of the alloy to bond the metal member directly to the ceramic substrate.